							Err	
	Туре	L#	Hits	Search Text	DBs	Time Stamp	Comments ion	ro
1	IS&R	L1	749	(429/212,213).CCLS.	USPA T; US-P GPUB	2003/03/3 1 18:57	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	0
2	BRS	L2	100	1 and (plasticizer plasticizing plasticating)		2003/03/3 1 18:58		0
3	BRS	L3	82	2 and ((electrode anode cathode) with (thick thickness))		2003/03/3 1 19:50		0
4	BRS	L4	40	3 and ((electrode anode cathode) with (Pore porosity porous micropore microporous microporosity))	USPA T; US-P GPUB	2003/03/3 1 19:04		0
5	BRS	L5	42	3 not 4	USPA T; US-P GPUB	2003/03/3 1 19:50		0

	Туре	L #	Hits	Search Text	DBs	Time Stamp	Comment s	Error Definition	ro
1	IS&R	L2	478	(429/213).CCLS.		2003/10/0 8 16:59			0
2	IS&R	L3	1	("6551747").PN.	USPA T	2003/10/0 8 16:19		•	О
3	BRS	L4	11	("3520729" "4324828" "5180642" "5571636" "5582935" "5667916" "5716422" "5744258" "6045942" "6258473").PN.	USPA T	2003/10/0 8 16:17			0
4	IS&R	L5	1149	(429/212,213,211).CCL S.	USPA T; US-P GPUB	2003/10/0 8 16:20		·	0
5 .	IS&R	L6	1061	(264/176.1).CCLS.	US-P GPUB	2003/10/0 8 16:20			0
6	BRS	L7	2210	5 6	USPA T; US-P GPUB	2003/10/0 8 16:20			0
7	BRS	L8	118	7 and @PD>20030315	USPA T; US-P GPUB	2003/10/0 8 17:15			0
8	BRS	L9	63	2 and (thickness with collector)	USPA T; US-P GPUB	2003/10/0 8 16:21		·	0
9	BRS	L10	40	2 and (thick with collector)	USPA T; US-P GPUB	2003/10/0 8 16:21			0
10	BRS	L11	77	9 10	USPA T; US-P GPUB	2003/10/0 8 16:21			0
11	BRS	L12	77	11 and (thickness thick)	USPA T; US-P GPUB	2003/10/0 8 16:22			0
12	BRS	L13	88	8 not 2	USPA T; US-P GPUB	2003/10/0 8 17:15			0
13	BRS	L14	88	13 not 12	USPA T; US-P GPUB	2003/10/0 8 17:15		·	0
14	BRS	L15	61	14 and (thick thickness)	USPA T; US-P GPUB	2003/10/0 8 17:18			0

	Туре	L #	Hits	Search Text	DBs	Time Stamp	Comment s	Error Definition	ro rs
15	BRS	L17	2488	H01M004/60		2003/10/0 8 17:20			0
16	BRS	L18	117	17 and (thick thickness)		2003/10/0 8 17:20			0
17	BRS		89	17 and volume		2003/10/0 8 17:20			0
18	BRS	L21	86	19 and (battery cell electrode anode cathode)	EPO; JPO; DERW ENT	2003/10/0 8 17:21			. 0
19	BRS	L20	114	18 and (battery cell electrode anode cathode)	EPO; JPO; DERW ENT	2003/10/0 8 17:35			0
20	BRS	L22	80	21 not 20		2003/10/0 8 17:35			0
21	BRS	L23	241	(FUJIWARA near3 MASAKI).in.	USPA T; US-P GPUB; EPO; JPO; DERW ENT	2003/10/0 8 17:41			0
22	BRS	L24	392	(NAKAGAWA near3 YUJI).in.	USPA T; US-P GPUB; EPO; JPO; DERW ENT	2003/10/0 8 17:42			0
23	BRS	L25	38	(KUROSAKI near3 MASATO).in.	USPA T; US-P GPUB; EPO; JPO; DERW ENT	2003/10/0 8 17:43			0
24	BRS	L26	26	(KANEKO near3 SHINAKO	USPA T; US-P GPUB; EPO; JPO; DERW ENT	2003/10/0 8 17:44		·	0

	Туре	L #	Hits	Search Text	DBs	Time Stamp	Comment s	Error Definition	Er ro
25	BRS	L27	48	(HARADA near3 GAKU).in.	USPA T; US-P GPUB; EPO; JPO; DERW ENT	2003/10/0 8 17:45			0
26	BRS	L28	277	(NISHIYAMA near3 TOSHIHIKO).in.	USPA T; US-P GPUB; EPO; JPO; DERW ENT	2003/10/0 8 17:45			0
27	BRS	L29	854	23 24 25 26 27 28	USPA T; US-P GPUB; EPO; JPO; DERW ENT	2003/10/0 8 17:46			0
28	BRS	L30	205	29 and (Battery cell electrode anode cathode)	USPA T; US-P GPUB; EPO; JPO; DERW ENT	2003/10/0 8 17:46		-	0
29	BRS	L31	77	30 and H01M\$8	USPA T; US-P GPUB; EPO; JPO; DERW ENT	2003/10/0 8 17:46			0
30	BRS	L32	26	31 and (thick thickness volume)	USPA T; US-P GPUB; EPO; JPO; DERW ENT	2003/10/0 8 17:47		·	0

	Туре	L#	Hits	Search Text	DBs	Time Stamp	Comment s	Error Definition	Er ro rs
31	BRS	L33	25	32 not 22	USPA T; US-P GPUB; EPO; JPO; DERW	2003/10/0 8 17:47			0
32	BRS	L34	25	33 not 15		2003/10/0 8 17:47			0